

Case Study

Escape of Liquids

As is an all too often occurrence, a flexi-hose bursts under a sink and water damage is done to the kitchen, joinery and timber floor. When it happens in a multi-story home this can pose a multitude of other issues. Further, when the timber finish is high gloss, and the customer has high expectations of the result, it is fantastic when we over deliver on their expectations. Great work Mike Hessel and your team for this great repair in time for Christmas!



Front Elevation



Kitchen and floor



Water damaged floor



A great repair starts with great preparation



Taping and securing of cupboards to prevent dust



Sanding complete



First coat being applied



First coat finished



High gloss timber floor after repair



High gloss finish on timber floor in kitchen



Kitchen repairs complete



High gloss timber floor after repair



Repairs completed under sink



Close-up of completed repairs for insurer